

# INFORMATION BULLETIN


## NEW SEAT PAN ENDCAP

### INTRODUCTION


Effective September 1<sup>st</sup>, 2022, the contents of the Service Kit S-0146 has changed. Instead of containing (1x) A9505, (1x) E00094, and (2x) E00034, **the kit now contains (2x) 1001061**. The part number remains S-0146.

### DETAILS

**BEFORE**  
Part # S-0146



**NOW**  
Part # S-0146



### Corresponding updates

The Parts Manual will be modified in its next revision at a later date.